
Commodity is loaded
Pre-cool
Pulling down
USDA MAX temperature
Final set point reached
Commodity is unloaded
Maintaining final set point
Warm up
C/T Period Maintaining C/T Set point
C/T Period started
C/T period Passed
ARA2337